



FACTORY APPROVAL CERTIFICATE

n°MGG28072501

Client's name and address: **DİKKAN GEMİ VE ENDÜSTRİYEL VANA SANAYİ TİC. A.Ş. Kemalpaşa Osb Mahallesi İzmir Kemalpaşa Asfaltı Cad.No:30/1**

Name and address of the factory: **DİKKAN GEMİ VE ENDÜSTRİYEL VANA SANAYİ TİC. A.Ş. Kemalpaşa Osb Mahallesi İzmir Kemalpaşa Asfaltı Cad.No:30/1 Kemalpaşa - İzmir / TURKEY**

Type(s) of product and component manufactured: **SHIPSIDE VALVE (DN15 To DN500) Globe Valves SDNR - Straight and Angle type(DN15 to DN500) GATE VALVE (DN40 to DN250) CHECK VALVE (DN50 to DN150) BUTTERFLY VALVE (DN50 to DN700)**

Monthly production: **200 tons**

After examination of the following documents:

- Dikkan Vana - Check Valve DNV Type Approval -TAP0000154rev1
- Dikkan Vana-Butterfly Valve DNV Type Approval -Certificate No: TAP00002HY
- Dikkan Vana -Gate Valve DNV Type Approval -Certificate No: TAP0000152rev1
- Type Approval Certificate Shipline Valve- Certificate number: 21134/D0 BV
- Type Approval Certificate Check Valves, Non-Return Valves - Certificate number: 21133/D0 BV
- ISO 9001 :2015 , Certification Date : 23-09-2024 Cert Number : TR013655
- ISO 14001 :2015 Certification Date : 23-09-2024 Cert Number : TR013657,
- ISO 45001 :2018 Certification Date : 23-09-2024 Cert Number : TR013656.
- Factory Audit Report n° MGG28072501 EN1074 Dikkan dated 28.07.2025

the undersigned, Inspector to Bureau Veritas, certifies that the above factory meets the applicable requirements for the production of the product and associated components referenced above.

This approval remains valid as long as no significant changes are made to the audited facility, its production rate and its quality system. These conditions are assessed during each inspection of series.

This approval is an integral and indissociable part of the certification process managed by Bureau Veritas as defined in BV procedure GM SI 210.

Inspected by:

Name:MEHMET GAZİ GÜMGÜM

Signature:

Date of issue : 28.07.2025

Date of Expire : 28.07.2026

Checked by:

Name: ERSİN BASMACI

Signature:

Inspection centre: BV TURKEY

